

**TABLE 2.7: OPERATOR CONTRIBUTING CIRCUMSTANCES
IN CONSTRUCTION ZONE CRASHES, 2006**

CONTRIBUTING CIRCUMSTANCES	2006	
	N	%
Failure to yield row	6	7.7%
Disregarded traffic signs, signals, road markings	1	1.3%
Excessive speed	0	0.0%
Driving too fast for conditions	7	9.0%
Improper turn	3	3.8%
Wrong side or wrong way	1	1.3%
Followed too closely	15	19.2%
Failure to keep in proper lane	3	3.8%
Operating vehicle in careless or reckless manner	1	1.3%
Swerving or avoiding	3	3.8%
Under the influence of medication/drugs/alcohol	2	2.6%
Visibility obstructed	7	9.0%
Inattention	15	19.2%
Distracted	0	0.0%
Fatigued, asleep	1	1.3%
Operating defective equipment	0	0.0%
Distraction caused by technology	0	0.0%
Other improper action	5	6.4%
Unknown	8	10.3%
TOTAL	78	100.0%

Note: Cumulative data are not presented as a result of changes in crash cause codes.
Cases with missing cause are excluded.

FIGURE 2.1: CONSTRUCTION ZONE CRASHES 2002 - 2006

